#### JUMO GmbH & Co. KG

 
 Delivery address:
 Mackenrodtstraße 14, 36039 Fulda, Germany

 Postal address:
 36035 Fulda, Germany

 Phone:
 +49 661 6003-0

 Fax:
 +49 661 6003-607

 e-mail:
 mail@jumo.net

 Internet:
 www.jumo.net
 JUMO Instrument Co. Ltd.

JUMO House Temple Bank, Riverway Harlow, Essex CM 20 2TT, UK Phone: +44 1279 635533 Fax: +44 1279 635262 e-mail: sales@jumo.co.uk Internet: www.jumo.co.uk

#### JUMO PROCESS CONTROL INC.

885 Fox Chase, Suite 103 Coatesville PA 19320, USA Phone: 610-380-8002 1-800-554-JUMO Fax: 610-380-8009 e-mail: info@JumoUSA.com Internet: www.JumoUSA.com



Data Sheet 70.7040

Page 1/8

# JUMO dTRANS T04 Four-wire Transmitter, settable via DIP switch/PC setup program

for connection to Pt100/Pt1000 resistance thermometer or potentiometer; rail-mounted for building into control cabinets


## **Brief description**

These transmitters are designed for industrial applications and are used to measure the temperature or resistance through a Pt100 or Pt1000 resistance sensor or potentiometer in 2-wire or 3-wire circuit connection.

The 0 - 20 mA, 4 - 20 mA or 0 - 10 V output signal is available linear with temperature/ resistance. The continuous analog signal path enables a fast reaction of the output to a temperature change (analog continuous measurement instead of digital sampling rate). This results in a low-noise output signal that is immune to interference. High precision, even with small ranges, is ensured by the range-specific gain adjustment.

The transmitter can be set either on the instrument itself, via DIP switch, or through the PC setup program.

## **Block structure**







The chosen measuring range and output response can be set via DIP switch. Using the PC setup program, additional ranges and parameters are configurable.



dTRANS T04 Type 707040/...



## **Key features**

- Measuring range selectable via DIP switch or through the PC setup program
- Choice of signal output:
   0 10V, 0 20mA or 4 20mA
- Fast response, thanks to continuous analog measurement
- Low-noise current signal, immune to interference
- Electrical isolation between input, output / mains supply
- Current/voltage output

## **Technical data**

### Input

Measurement input	Pt100 EN 60 751	Pt1000 EN 60 751	Potentiometer		
Range limits	-200 to +850°C	-200 to +850°C	0 — 11000Ω		
Connection circuit	I	2- and 3-wire circuit			
Configuration	through E	DIP switch or using the PC setup	program		
Shortest span	25°C	25°C	250Ω		
Largest span	1050°C	1050°C	11000Ω		
Range start for shortest span	-50°C to +20°C	-50°C to +20°C	0 — 500Ω		
Range start for other spans	see rar	see range organization on Page 5 and Page 6			
Unit	°C (°F settable through the PC setup program)	°C (°F settable through the PC setup program)	Ω		
Sensor lead resistance for 3-wire connection		≤ 11Ω per conductor			
Sensor lead resistance for 2-wire connection		factory-set: $0\Omega$ lead resistance, adjustable through the PC setup program			
Sensor current	≤ 0.5mA	≤ 0.1mA	≤ 0.1 mA		
Sampling rate	continuous measurement (analog signal path)				

### Output

Measurement input	Pt100 EN 60 751	Pt1000 EN 60 751	Potentiometer	
Output signal	selectable through DIP switch or PC setup program			
- current:	proportional DC current 0 — 20mA or 4 — 20mA			
- voltage:	DC voltage 0 – 10V			
Transfer characteristic				
- for resistance thermometer:		linear with temperature		
- for potentiometer:		linear with resistance		
Transfer accuracy		$\leq \pm 0.1 \%^{1}$		
Residual ripple		$\leq \pm 0.2\%^{1}$		
Burden (with current output)	≤750Ω			
Burden error	$\leq \pm 0.01 \% / 100 \Omega^1$			
Current limiting	> 21.6mA — < 28mA (24mA typical)			
Load (with voltage output)	≥ 10kΩ			
Load error	$\leq \pm 0.1\%^{1}$			
Voltage limiting		> 11V — < 14V (12V typical)		
Settling time on a temperature change		≤ 40msec		
Settling time after switch-on or reset	≤ 200 msec			
Calibration conditions	230V AC or 24V DC (depending on the supply) at 23°C (± 5°C)			
Calibration accuracy	$\leq \pm \ 0.3 \ \%^{1,2} \ \text{or} \leq \pm \ 0.3 \ ^{\circ}\text{C}^2$	$\leq \pm 0.3\%^{1,2} \text{ or } \leq \pm 0.3^{\circ}C^{2}$	$\leq \pm 0.3\%^{1}$	
Supply voltage error	$\leq \pm 0.05\%^{1}$			

<sup>1</sup> All data refer to the range end value 10V or 20mA <sup>2</sup> The larger value applies

### Measuring circuit monitoring

Underrange: - current output 4 — 20mA - current output 0 — 20mA - voltage output 0 — 10V	falling to $\leq$ 3.6mA < 0mA (-0.05mA typical) < 0V -0.6V typical)
Overrange - current output 4 — 20mA - current output 0 — 20mA - voltage output 0 — 10V	rising to > 21.6mA — < 28mA (24mA typical) rising to > 21.6mA — < 28mA (24mA typical) rising to > 11V — < 14V (12V typical)
Probe short-circuit: - current output 4 — 20mA - current output 0 — 20mA - voltage output 0 — 10V	≥ 1.5mA — ≤ 3.6mA (2mA typical) < 0mA (-0.05mA typical) < 0V (-0.6V typical)

Probe and lead break:	Signal is configurable.	
- current output 4 — 20mA	positive signal: > 21.6mA — < 28mA (24mA typical)	
	negative signal: $\geq$ 1.5mA — $\leq$ 3.6mA (2mA typical)	
<ul> <li>current output 0 — 20mA</li> </ul>	positive signal: > 21.6mA — < 28mA (24mA typical)	
	negative signal: $< 0$ mA (-0.05mA typical)	
<ul> <li>voltage output 0 — 10V</li> </ul>	positive signal: $> 11 V - < 14 V$ (12V typical)	
	negative signal: < 0V (-0.6V typical)	

### **Electrical data**

Supply voltage	110 - 240V AC +10/-15%, 48 - 63Hz	20 — 53V AC/DC, 48 — 63Hz
Power consumption	4VA	3VA
Electrical safety	to EN 61 010, Part 1 overvoltage category III, pollution degree 2, for switching cabinet mounting to EN 50 178	to EN 61 010, Part 1 protection class III, for operation with SELV/PELV circuits
Test voltage	3700V	500V
Electrical isolation	The supply is electrically isolated from the input and the output. There is no electrical isolation between input, output and setup connector.	The supply is electrically isolated from the input and the output. There is no electrical isolation between input, output and setup connector.

### **Environmental influences**

-25 to +55°C
-40 to +90°C
rel. humidity $\leq$ 85%, no condensation
$\leq \pm 0.01 \% / °C^{1}$
EN 60721-3-3 3K3
rel. humidity $\leq$ 85% annual average, no condensation
according to GL Characteristic 2
EN 61 326
Class B
to industrial requirements
IP20 to EN 60 529

<sup>1</sup> All data refer to the range end value 10V or 20mA

### Housing

Material	polycarbonate	
Flammability class	UL 94 V0	
Dimensions (W x H x D)	22.5 x 93.5 x 60mm	
Screw terminal	2,5mm <sup>2</sup> wire cross-section / 2.5mm wire dia.	
Mounting	on 35mm x 7.5mm DIN rail to EN 60 715 A.1, for installation in control cabinets	
Operating position	unrestricted	
Weight	approx. 100g	

## PC setup program

The PC setup program is used for configuration and fine adjustment of the transmitter from a PC (e.g. when the sensor drifts). Connection is through the PC interface with TTL/RS232 converter and adapter and the setup interface of the transmitter. In order to configure the transmitter, it must be connected to the supply.

#### **Configurable parameters**

- TAG number (14 characters)
- response to probe and cable break
- range start, range end
- output signal 0(4) 20mA or 0 10V
- lead resistance for 2-wire circuit

### Fine adjustment

Fine adjustment means correction of the output signal of a configured transmitter; systematic errors such as those caused by an unsuitable probe mounting can be compensated. The signal can be adjusted in the range  $\pm 0.2$  mA for current output and  $\pm 0.1$  V for voltage output. Fine adjustment can only be carried out through the setup program.

#### Hardware and software requirements

The following hardware and software requirements must be met for installing and operating the PC setup program:


- IBM-PC or compatible PC with Pentium processor or higher
- 64 MB main memory
- 15MB available on hard disk
- CD-ROM drive
- 1 free serial interface
- Win 98, ME or Win NT4.0, 2000, XP

## **DIP** switch configuration

	Function or measuring range	Function or measuring range		D	IP s	wite	ch	
	for Pt100 and Pt1000	for potentiometer	1	2	3	4	5	
	PC setup <sup>1</sup>	PC setup <sup>1</sup>						T
	Output 0 – 10V	Output 0 – 10V	•					
	Output 0 — 20mA	Output 0 – 20mA		•				
	Output 4 – 20mA	Output 4 – 20mA	•	•				-
	Range 0 to 50°C	Range 0 — 500 $\Omega$			•			-
	Range 0 to 60°C	Range 0 – 1 k $\Omega$				•		-
	Range 0 to 100°C	Range 0 – $2k\Omega$			•	•		-
	Range 0 to 150°C	Range 0 – $3k\Omega$					•	
10V	Range 0 to 200 °C	Range 0 – $4k\Omega$			•		•	
	Range 0 to 250 °C	Range 0 — $5k\Omega$				•	•	-
	Range 0 to 300 °C	Range 0 – 6kΩ			•	•	•	-
	Range 0 to 400 °C	Range 0 – 7k $\Omega$						-
	Range 0 to 500 °C	Range 0 – 8kΩ			•			-
	Range 0 to 600 °C	Range 0 – 9k $\Omega$				•		-
	Range -20 to +80°C	Range 0 – 10kΩ			•	•		
	Range -30 to +60°C	Range 0 – 11kΩ					•	-
	Range -30 to +70°C				•		•	-
	Range -40 to +60°C					٠	•	-
	Range -50 to +50°C		1		•	•	•	-

<sup>1</sup> When configuring through the PC setup program, the input **and** output must be configured from the PC.

## Measuring range organization (resistance thermometer)



All the possible range-start values in relation to the range span are contained within the gray area.


#### range span = range end - range start

Example:

range start = -50°C, range end = 275°C range span = range end – range start = 275°C - (-50°C) = 325°C

Please note: When selecting the range start, make sure it lies within the gray area.

## Measuring range organization (potentiometer)



### Measuring range start $\Omega$

All the possible range-start values in relation to the range span are contained within the gray area.

range span = range end - range start


Example:

range start = 100  $\Omega$ , range end = 3100  $\Omega$  range span = range end – range start = 3100  $\Omega$  – 100  $\Omega$  = 3000  $\Omega$ 

Please note: When selecting the range start, make sure it lies within the gray area.


Page 7/8







## **Dimensions**

4 (+)







## Order details: JUMO dTRANS TO4

Four-wire transmitter, settable via DIP switch/PC setup program

				(1) Basic version <sup>1</sup>
			707040/1	dTRANS T04 for Pt100 resistance thermometer
			707040/2	dTRANS T04 for Pt1000 resistance thermometer
			707040/3	dTRANS T04 for potentiometer
				(2) Input
x	x		888	factory-set <sup>2</sup> (3-wire circuit, 0 to 100°C)
		х	888	factory-set <sup>2</sup> (3-wire circuit, $0 - 1 k\Omega$ )
х	х	х	999	configuration to customer specification (please specify in plain text) <sup>3</sup>
				(3) Output
х	х	х	888	factory-set (0 – 20mA)
х	х	х	999	setting to customer specification (please specify in plain text) $^3$
				(4) Supply
х		х	22	20 – 53V AC/DC, 48 – 63Hz
х	х	х	23	110 — 240V AC +10/-15%, 48 — 63Hz
				(1) (2) (3) (4)
Or	der	code		
Order example			ole	707040/1 - 888 - 888 - 23

 $^{1}\,$  It is not possible to switch between the sensor types.

<sup>2</sup> Additional measuring ranges are selectable via DIP switch or PC setup program (see Page 4).

<sup>3</sup> Please check whether the required measuring range and output can be set via DIP switch. In such a case, "factory-set" can be ordered.

### Standard accessory

- Operating Manual

-

### Accessories - Data Sheet 70.9700

PC setup program, multilingual	70/00448774
PC interface with TTL/RS232 converter and adapter (socket)	70/00350260
PC interface with USB/TTL converter, adapter (socket) and adapter (pins)	70/00456352

Sales No.